The following is the agenda item that I would like to add to next months Board Meeting. I have support on this item from McNabb.

Topic: Insufficient Fire Flow in along Balcones Dr.

It has come to my attention that the fire flow in the neighborhood surrounding Balcones Dr from 35th street to Perry Lane is not sufficient to meet the minimum requirement of 1000 gpm at 20psi as required for single family homes by the IFC2012 Appendix B. I would like a representative of WW&W and AFD to address this issue and provide the board with recommendation on how to correct this issue. I will forward a water flow test that I received for a property at 4600 Laurel Canyon. There is a similar poor report for a property at 3420 Mount Barker but I don't have a copy of that report.



## **AUSTIN FIRE DEPARTMENT - FIRE PREVENTION DIVISION**

**Engineering Services Section** One Texas Center, Ste 200 - 505 Barton Springs Road Austin, Texas 78704



Telephone (512) 974-0160 - Facsimile (512) 974-0162

TEST DATE:	4/17/15			COMPANY:	PREV
TIME:	1700 HRS		SHIFT:	OFFICER:	N/N
		RESI	IDUAL HYDRANT		
MAP GRID#	HYDRANT#		PIPE INTERSECTION #	MAIN SIZE	AFD BOX #
H27	118405		604	6	1905
BLK#	DIRECTION		STREET NAME		ТҮРЕ
4600			LAUREL CANYON		DR
STATIC PRESSU	RE (PSI):	94	RESIDUAL	PRESSURE (PSI):	24
COMMENTS:	, , , , , , , , , , , , , , , , , , ,				
	THE PLANT				
		FI	OW HVDD ANT		
			LOW HYDRANT		
MAP GRID#	HYDRANT#		PIPE INTERSECTION #	MAIN SIZE	
MAP GRID # H27	HYDRANT # 119131			MAIN SIZE 6	AFD BOX #
A STATE OF THE PARTY OF THE PAR			PIPE INTERSECTION #		
H27	119131		PIPE INTERSECTION # 3156		1905
H27	119131  DIRECTION	90	3156 STREET NAME SPANISH OAK		1905 TYPE
H27 <u>BLK#</u> 3400	119131  DIRECTION		3156 STREET NAME SPANISH OAK VELOCITY	PRESSURE (PSI):	1905 <u>TYPE</u> DR
H27 <u>BLK#</u> 3400	119131  DIRECTION		3156  STREET NAME SPANISH OAK  VELOCITY  dc = 6 straig	6	1905 TYPE DR
H27 <u>BLK#</u> 3400	119131  DIRECTION		3156  STREET NAME SPANISH OAK  VELOCITY  dc = 6 straig w/45	PRESSURE (PSI):  discharge coefficient  at 2½" butt = .9  elbow = .75	TYPE DR
H27 <u>BLK#</u> 3400	119131  DIRECTION		3156  STREET NAME SPANISH OAK  VELOCITY  dc = 6 straig w/45	PRESSURE (PSI):  discharge coefficient nt 2%" butt = .9	1905 <u>TYPE</u> DR
H27 <u>BLK#</u> 3400	119131  DIRECTION		3156  STREET NAME SPANISH OAK  VELOCITY  dc = 6 straig w/45	PRESSURE (PSI):  discharge coefficient  at 2½" butt = .9  elbow = .75	1905 <u>TYPE</u> DR 15

NOTE: This information represents the water supply characteristics in the immediate area on the date and time tested. The City of Austin does not guarantee this data will be representative of the water supply characteristics at any time in the future. It is the requesting party's responsibility to ensure that this test information is appropriate to the location of the project in question and that any differences in elevation between the test location and project are accounted for and included in the hydraulic calculations.

